



U.S. Department
of Transportation
Federal Aviation
Administration

Small Airplane Directorate
Atlanta Aircraft Certification Office
One Crown Center, Suite 450
1895 Phoenix Boulevard
Atlanta, GA 30349

APR 21 2000

Mr. John Sherman
Parachute Laboratories, Inc.
Suite 106
1665 Lexington Avenue
Deland, FL 32720

Dear Mr. Sherman:

This is in response to your January 24, 2000, request for Federal Aviation Administration authorization to correct part numbers originally approved in your October 6, 1993 and April 11, 1997, TSO authorization letters. This letter does not change the effective date of your original approval; simply corrects the part numbers shown in the original approval. Further, this letter has no effect on your ability to assure compliance with 14 CFR, part 21, subpart O, including 14 CFR, part 21.143 and TSO C23c.

Your original Statement of Conformance, Quality Control Manual, and data listed in your original TSO authorization are acceptable and will still be retained for this authorization.

Effective this date, you are authorized to identify the Tandem Harness/Container System, Part Number TAN002 (formerly Part Number SSE001); and the Tandem Reserve 400 and 500 Canopies, Part Number SSE200-4 and SSE200-5, respectively (formerly Part Numbers SSE220-4 and SSE200-5) with the appropriate TSO markings required by the applicable TSO and 14 CFR, part 21, subpart 21.607(d).

This authorization is not transferable to another person or location and is effective until surrendered, withdrawn, or otherwise terminated by the Administrator.

Your responsibilities as a holder of a TSO authorization are outlined in 14 CFR, subpart 21.3 and 14 CFR, part 21, subpart O. Any design change made to the TSO'd item must be forwarded to this office as outlined in 14 CFR, part 21.611, with minor change submittal intervals not to exceed six months.

The Aerospace Engineer for this authorization is Don Young, telephone number (770) 703-6079. The Technical Information Specialist is Lorraine Bush, telephone (770) 703-6044.

Sincerely,

Paul C. Sconyers
Associate Manager
Atlanta Aircraft Certification Office